OUT55001 19 FEB 1965

21

1965 FEB 8

042

P Ø82Ø5ØZ

FM NPIC WASHDC TO

TO RUCSC/SAC OFFUTT AFB OMAHA NEB

RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAA/2D RTS BARKSDALE AFB LA

RHEKDA/DIA WASHDC

RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF

RUWGAA/2AF BARKSDALE AFB LA

BT

S E C R E T CITE NPIC 3810.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

CAMERA B 15 WAS USED IN MISSION 3988 FLOWN ON 6 FEBRUARY
 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

- 2. ORIGINAL NEGATIVE:
 - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: ROLLER CHATTER IS PRESENT ALONG BOTH SIDES OF THE FILM IN THE FIRST 300 FRAMES. EDGE STATIC EXISTS ALONG THE OUTBOARD EDGE FOR THE FIRST 200 FRAMES. A CONTINUOUS PLUS DENSITY LINE OCCURS 3.2" FROM THE INBOARD EDGE THROUGHOUT THE MISSION.

 INK TRANSFER FROM THE LEADER IS PRESENT ON FRAMES 0001 AND 0300.

 A DIG WITH ASSOCIATED SCRATCHES EXISTS IN FRAME 0900. TRANSVERSE FOG STREAKS APPEAR ON THE LAST TWO FRAMES. MANUFACTURING SPLICES OCCUR IN FRAMES 228 AND 1224.

COPIES RECEIVED Act Rec Office CyNo. Master File CS ADMIN SEC BR FRDS CSD 120 PD PSD TID PAG 1 .. . X X .. \$ WIF? Destroyed

- C. 9L SIDE: INBOARD EDGE STATIC IS PRESENT IN THE FIRST

 125 FRAMES. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1954.

 FRAME 1500 CONTAINS AN INK SMEAR FROM THE TITLING ON THE HEAD IDENT.
- D. BOTH SIDES: THE FRAMES ARE TITLED FROM 0000 TO 2143 ON EACH SIDE.
- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERICS.
 - B. THE PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS DEGRADED APPROXIMATELY 45 PERCENT OF THE MISSION.

 GP-1
 SECRET

-- END OF MESSAGE--